

# Environmental Monitoring Program

## Ardmore Park Quarry Project


### Site information

Project	Ardmore Park Quarry Project
Address	5152 Oallen Ford Road, Bungonia NSW
Project approval	PA 07_0155 (Modification 3)
Environmental Protection Licence	13213

### Environmental monitoring points

Monitoring Point	EPL Number	Type	Frequency
Inverary	1	Deposited dust	Monthly
Olsiers	2	Deposited dust	Monthly
Lochmoor Lodge	3	Deposited dust	Monthly
Front Gate	4	Deposited dust	Monthly
BHAP1	5	Monitoring bore	Depth monthly, sample annually
BHAP5	6	Monitoring bore	Depth monthly, sample annually
BHAP6	7	Monitoring bore	Depth monthly, sample annually
BHAP10	8	Monitoring bore	Depth monthly, sample annually
BH6	14	Monitoring bore	Depth monthly, sample quarterly
BHS1	18	Monitoring bore	Depth monthly, sample quarterly
BHS2	19	Monitoring bore	Depth monthly, sample quarterly
BHS3	20	Monitoring bore	Depth monthly, sample quarterly
BHS4	21	Monitoring bore	Depth monthly, sample quarterly
BHS5	22	Monitoring bore	Depth monthly, sample quarterly
BHS6	23	Monitoring bore	Depth monthly, sample quarterly
Phils Spring	15	Spring	Flow monthly, sample quarterly
Southern Spring	16	Spring	Flow monthly, sample quarterly
Western Spring	17	Spring	Flow monthly, sample quarterly
Ardmore Park AWS	NA	Weather Station	Continuous

# Monitoring points



**Ardmore Park Quarry Environmental Monitoring Points**

- Monitoring Points**
- Dust Gauge
  - Bore (Rock)
  - Bore (Sand)
  - Spring
  - Weather Station

- Multiquip Quarries
- Lot Boundary
- Extraction Area
- 🏠 Residential Receiver

